



BKN - BD95642 - Kit de Distribución

Hyundai / Mitsubishi

Num. de dientes: 55

Ancho [mm]: 12.7