

WAT - BHU52Y - BOMBA HIDRAULICA HYUNDAI TRAJET 2.0

Ø Polea [mm]: 140

Tipo de servicio: Hidráulico



